


Fittings


Copper Capillary

Slip
Coupler




600M

Straight
Coupler




601M CXC

Reducing
Coupler




601M CXC

Straight Tap
Connector



601MTCFIXC

Straight
Coupler




603M CXFI

Straight Red.
Coupler



603M CXFI

Fitting
Reducer




601-2M MCXC

Straight
Coupler



604M CXMI

Straight Red.
Coupler



604M CXMI

Elbow
45°



606M CXC

Elbow
90°



607M CXC

Reducing
Elbow



607M CXC

Elbow 90°




607 2M MCXMC

Bent Tap
Connector



607M TC CXFI

Elbow
90°



707 - 3M CXFI

Reducing Elbow
90°



707 - 3M CXFI

Wallplate
Elbow



707M - 3-5M CXFI

Elbow 90°



707M - 4M CXMI

Reducing Elbow 90°



707M - 4M CXMI

Tee



611M CXCXC

Fittings


Copper Capillary

Reducing Tee



611 M CXCXC

Reducing Tee




611 M CXCXC

Reducing Tee




611 M CXCXC

Reducing Tee




611 M CXCXC

Reducing Tee



611 M CXCXC

Pitcher Tee



711 M-P CXCXC

Tee




712M - CXCXFI

Tube End Cap




617 M

Union Coupler




733M CXC

Union Coupler



733-3M CXFI

Union Coupler



733-4M CXFI

Cross




735M - CXCXC

Full crossover



636M CXC

Return Bend



639M CXC

Single Tube Cap



9826C

Tube Strap



9828S

SOLDERS

- THE USE OF RECOMMENDED SOLDERS AND SOLDERING TECHNIQUES WILL ENSURE AN EXCEPTIONALLY STRONG JOINT.
- AVOID SOLDERS CONTAINING LEAD AS APART FROM BEING A HEALTH HAZARD, THEY HAVE RELATIVELY LOW SHEAR STRENGTH
- RESIN AND ACID CORE SOLDERS SHOULD ALSO NOT BE USED
- THE LOW HEAT REQUIRED TO MELT SOFT SOLDER (2400) PREVENTS THE FORMATION OF DELETERIOUS FILMS THUS AVOIDING THE POSSIBILITY OF PITTING CORROSION.